

Items Needed to Perform Update

- A Windows Operating System PC (Windows 7 and up)
- Spektrum SPMXCA200 Avian & Firma Smart ESC Programming Box ([sold separately](#))
- Spektrum Firma Smart ESC SPMXSE1160 (Retail Version / DBXL-E 2.0) or SPMXSE1160CP (ARRMA Kraton 8S ESC)
- Spektrum Firma Smart ESC SPMXSE1150 (Retail Version)
- Spektrum Firma Smart ESC SPMXSE1130 (Retail Version / Losi Tenacity DB Pro)

Step by Step


Download the latest Firma 160A CP (**SPMXSE1160CP** – Kraton 8S) Smart ESC firmware updater [here](#)

Download the latest Firma 160A (**SPMXSE1160** – Retail Version / DBXLE) Smart ESC firmware updater [here](#)


Download the latest Firma 130A (**SPMXSE1130** – Retail Version / Losi Tenacity DB Pro) Smart ESC firmware updater [here](#)

Download the latest Firma 150A (**SPMXSE1150** – Retail Version) firmware updater [here](#)

Once downloaded extract the .ZIP file to a location that you can easily find, we suggest the Desktop

Locate the Spektrum USB Link application and open the file:  **Spektrum USB Link**

You will be presented with this screen:




Firma Smart ESCs

Update Instructions and Change Log

2020 – June - 12



- Plug the appropriate battery source into your Firma ESC to power on
- Connect the SPMXCA200 programmer to the Firma ESC through the fan port with the included three wire servo cable
- Connect the SPMXCA200 programmer to your PC via the included USB cable
- Power on your Firma ESC to connect the ESC to the Spektrum USB Link application



- Click the Firmware Upgrade tab
- Select the top version from the “Available Versions” drop down box then click the “Upgrade” button to perform the update

Information Upgrade

Device Type

Hardware Version

Firmware Version

Available Versions

Database Version: 04-12-2019

Once the **Upgrade** button has been selected to install the update on your Firma ESC a progress bar will appear on your computer screen. Please allow the update to completely finish then click OK to save the settings. You can disconnect and use your Firma ESC with the improved Firmware now.

Firma Smart ESCs

Update Instructions and Change Log

2020 – June - 12



Change Log

Firma 160A SPMXSE1160 -- Open Stock / DBXL-E 2.0	Firmware: B4.07
<ol style="list-style-type: none">1. Improves braking action2. Improves reverse action	
Firma 160A SPMXSE1160CP -- Kraton 8S	Firmware: B3.09
<ol style="list-style-type: none">1. Improve acceleration power	
Firma 150A SPMXSE1150 – Retail Version	Firmware: B2.11 (off-road) B2.12 (on-road)
<ol style="list-style-type: none">1. Improve acceleration power	
Firma 130A SPMXSE1130 – Retail Version / Losi Tenacity DB Pro	Firmware: B1.58
<ol style="list-style-type: none">1. Improve acceleration power	
Firma 160A SPMXSE1160 -- Open Stock / DBXL-E 2.0	Firmware: B4.02
<ul style="list-style-type: none">✓ Initial production version	
Firma 160A SPMXSE1160CP – Kraton 8S	Firmware: B3.02
<ul style="list-style-type: none">✓ Initial production version	
Firma 150A SPMXSE1150 – Retail Version	Firmware: B3.03
<ul style="list-style-type: none">✓ Initial production version	
Firma 130A SPMXSE1130 – Retail Version / Losi Tenacity DB Pro	Firmware 1.53
<ul style="list-style-type: none">✓ Initial production version	